

Diagnostic History

The Report is created by **LAUNCH X-431**

Vehicle Information

License #:

Year:2009.09

Make:BMW

Model:5 Series

VIN:WBANX52050C292056

Odometer:248290 km

Test Time:2026-04-07 04:30:51PM

Vehicle Software Version:V51.66

Diagnostic Application Version:V7.00.011

User Operation:Health Report > CAS (Car Access System - CAS/FEM/BDC)

Health Report > TCM (Transmission Control Module - EGS/DKG/SMG)

Health Report > SZL (Switch Center, Steering Column)

Health Report > CON (Controller)

Health Report > IC (Instrument Cluster - INSTR)

Health Report > LM (Lights Module)

DTC

DTC	Description	State
A0AA	CAS: Control-Unit Fault	Current
A11A	CAS: ELV Fault	Current
CF35	Messages From CAS, Receiver EGS, Transmitter CAS	History
CF25	Message (Seat Occupancy Seat Belt Buckle Contact) From SSFA, Receiver EGS, Transmitter ACSM/MRS5/DME-DDE/KOMBI	History
CF2A	Message (Vehicle Mode) From SZM, Receiver EGS, Transmitter KOMBI/SZM	History
9501	SZL: Steering-Angle Sensor Not Adjusted	Current
94C1	SZL: Coding-Data Error	Current
A3B2	Message Error (Terminal Status, 0x130), Receiver Instrument Panel, Transmitter CAS	History
E2D6	Message (Kilometre Reading, 0x330) Faulty, Receiver CON, Transmitter KOMBI	Current
9CC5	LM: No Message, LIN (RLS)	History